



NTSB National Transportation Safety Board



Engineering Design: Insights into Highway Bridge and Tunnel Disasters


INCOSE – Chesapeake Chapter
August 20, 2014
Laurel, MD

Earl F. Weener, Ph.D.
Member, NTSB


NTSB Mission

The NTSB is an independent US federal agency charged with determining the probable cause(s) of transportation accidents, making recommendations to prevent their recurrence, conducting special studies and investigations, and coordinating resources to assist victims and their families after an accident.

Generalized System Engineering V



Collapse of I-35 Highway Bridge Minneapolis, MN






I-35W Bridge


**Downtown
District**

Video Sequence of bridge collapse






General Description of the Bridge



General Description of the Bridge



Probable Cause of Failure

The inadequate load capacity, due to design error of the gusset plates at the “U10” connection points by the engineering consulting firm responsible for the bridge design, which failed under a combination of:

- 1) Substantial increases in the weight of the bridge, resulting from previous bridge modifications; and
- 2) Traffic and concentrated construction loads on the bridge the day of the collapse.


Contributing Probable Cause of Failure

Contributing to the design error was the failure of the engineering consulting firm's quality control procedures to ensure appropriate main truss gusset plate calculations were performed; and the inadequate design review by Federal and State transportation officials.

Contributing to the accident was the accepted practice by these officials of giving inadequate attention to gusset plates during inspections and excluding them from load rating analyses.

I-35W Bridge Information

Bridge deck
(roadway)



**North
Upper
Chord**

**South
Upper
Chord**


**Tension
Diagonal**

Vertical

**Compression
Diagonal**




National Transportation Safety Board




Bridge Modifications

- 1977 – modification to increase bridge deck thickness
 - Bridge dead load increase of 13.4%
- 1998 – modifications to the median barrier and outside railings
 - Bridge dead load increase of 6.1%

Placement of Additional Loads



Construction Work – Day of Accident




Piles of aggregate


Construction equipment
and vehicles

U10 west node


Drawing of Fractures in Node U10E West Gusset Plate




Dead Load of Original 1967 Bridge




After 1977 and 1998 Modifications




Loads at Time of Accident




Loads at Time of Accident




Step: construc Frame: 0



Step: construc Frame: 0




Accident Loads on 1-Inch-Thick Gusset Plates





U10 West and U10 East

Stress



U10 East



U10 West


Has higher stress
at the time of the
accident



Standards, Regulations and Guidance

- Federal Highway Administration
 - Inspection requirements (regulations)
 - Construction loading (technical advisories)
- AASHTO/AASHTO
 - Initial bridge design
 - Inspections
 - Bridge condition evaluations/load evaluations
- MN/DOT
 - Initial bridge design
 - Construction projects

2003 Photo



Compression
diagonal


Missed Opportunities

- Design, construction, and inspection guidance materials focused on members and other structural elements only.
- Bridge safety inspection engineer – noticed, but made poor assumptions and did not document.
- Evaluations by URS/U. of Minnesota, failed to identify bowing condition, although captured photographic evidence.
- Decision to allow staging of aggregates on bridge deck truss.

Follow-on

- Investigation revealed a number of other instances where questionable bridge designs have been certified and approved for construction.
 - 10 States acknowledged approving designs later found deficient
 - At the time, 2008, all but one of these approvals had occurred in the previous 10 years (most within the previous 6 years)

Generalized System Engineering V



Ceiling Collapse in I-90 Connector Tunnel Boston, MA

Ceiling Collapse in the Interstate 90 Connector Tunnel
Boston, Massachusetts
July 10, 2006



National
Transportation
Safety Board

ACCIDENT REPORT
NTSB/HAR-07/02
PB2007-916293





D Street





Source: Mass. State Police



Source: Mass. State Police



Source: Mass. State Police

Probable Cause of Failure

The use of an epoxy anchor adhesive with poor creep that could not sustain long-term loads.


The failure of the project consultants to identify creep as a critical long-term issue, and account for it in the design, specifications, and approval process for an anchoring system.

The failure of the epoxy provider to provide the consultants sufficient information to determine the suitability of the product to sustain long-term tensile loads.

Probable Cause of Failure


Contributing to the accident:

- Failure of the epoxy provider to identify the unsuitability of the epoxy in a previous anchor application.
- Failure of project contractors to continue to monitor the anchors, after the first instance of anchor displacement.
- Failure of the Turnpike authority to implement an inspection program.



Displaced Anchors






Missed Opportunities

- Construction project consultant's limitations on choice of anchoring system
- Lack of clarity on types of epoxy available/provided
- Insufficient approval review by design consultant – which failed to identify the type of epoxy and note the limits on its use.
- After initially discovering the displacement of anchors, failing to identify the cause.
- After taking some action, failing to follow up to ensure action was appropriate and issue resolved.

Question Assumptions

- Reliance on standards and testing that did not properly assess or account for key characteristics of critical infrastructure components
- Reliance on false assumptions, rather than focusing on actual, visual evidence.
- ***When the performance requirements change, the front-end V requirements need reassessment***

Generalized System Engineering V





NTSB